


BUILDING CERTIFICATE


The School building of EMRS at Killar P.O. Killar Tehsil Pangi District Chamba HP., was inspected by undersigned alongwith Junior Engineer concerned on dated 12/08/21. It has been observed that no earthquake resistant provisions have been adopted for this building and no structural drawings approved by the competent Government certified Engineer have been produced at the time of inspection. Moreover no assistance was taken from PWD for construction of this building. This structure is a non-engineered structure. Hence the structural safety of this building cannot be ensured specifically from earthquake resistant point of view. The department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances.


However as per visual inspection the building has been found safe at present i.e. 2021-22 only. No officer/official of this office will attend plea in any Hon'ble court of Law in case of any dispute.

Place... Killar

Date... 12/08/2021


Junior Engineer,
Killar Sub Division No-I,
HP.PWD. Killar (Pangi)


Assistant Engineer,
Killar Sub Division No-I,
HP.PWD. Killar (Pangi)


Executive Engineer,
Killar Division,
HP.PWD. Killar (Pangi)